# LaneAlert2x™
A Pavement Marking with a Message
LaneAlert 2x™ Application Quick Guide

1 Remove Existing Markings, Sealants or Curring Compounds*

2 Clean Surface of Debris, Dirt and Oils

**3** Layout and Mark Proper Alignment and Spacing

4 Preheat Surface to 225°F to 250°F Removing Moisture

5 Place and Melt Adhesive Panel to 360°F to 380°F to Molten State

6 Align and Apply Marking Panel on Top of Molten Adhesive Panel

7 Press Marking Evenly into the Adhesive Panel, by Gloved Hand, Float or Approved Roller

Do Not Apply Heat Directly Atop Marking Panel

8 Heat Perimeter Pavement to Seal Edges of Panels to Pavement and One Another

9 Test Adhesion of Panels and Pavement

10 Let Cool to < 100°F Degrees Before Traffic

<100° F

*See Detailed Surface Preparation Instructions

*Patented